



Master



Slave



| | |
|-----|----------------------------------|
| TP4 | GND |
| TP6 | Pin17/RXER (CLK-Out in TestMode) |
| TP7 | Pin20/CLK_IN_OUT |
| TP3 | GND |
| TP1 | Pin25/REF_CLK |



Link-Up Master

Link-Up Slave



No Link Master

No Link Slave